

Fig. 1.




Fig. 2.








Fig. 3.



Goussier Del.

Benard Sculp.

Forges, 2^e Section, Fourneau à Fer, Charger.